

## - - - PRESSURE CONVERSION CHART - - -

mB	in. Hg	mB	in. Hg	mB	in. Hg	mB	in. Hg
947	27,97	980	28,95	1013	29,92	1046	30,89
948	28,00	981	28,97	1014	29,95	1047	30,92
949	28,03	982	29,00	1015	29,98	1048	30,95
950	28,06	983	29,03	1016	30,01	1049	30,98
951	28,09	984	29,06	1017	30,04	1050	31,01
952	28,12	985	29,09	1018	30,07	1051	31,04
953	28,15	986	29,12	1019	30,10	1052	31,07
954	28,18	987	29,15	1020	30,13	1053	31,10
955	28,21	988	29,18	1021	30,16	1054	31,13
956	28,24	989	29,21	1022	30,19	1055	31,16
957	28,27	990	29,24	1023	30,22	1056	31,19
958	28,30	991	29,27	1024	30,24	1057	31,22
959	28,33	992	29,30	1025	30,27	1058	31,25
960	28,35	993	29,33	1026	30,30	1059	31,28
961	28,38	994	29,36	1027	30,33	1060	31,31
962	28,41	995	29,39	1028	30,36	1061	31,34
963	28,44	996	29,42	1029	30,39	1062	31,37
964	28,47	997	29,45	1030	30,42	1063	31,40
965	28,50	998	29,48	1031	30,45	1064	31,43
966	28,53	999	29,51	1032	30,48	1065	31,46
967	28,56	1000	29,54	1033	30,51	1066	31,49
968	28,59	1001	29,57	1034	30,54	1067	31,51
969	28,62	1002	29,60	1035	30,57	1068	31,54
970	28,65	1003	29,62	1036	30,60	1069	31,57
971	28,68	1004	29,65	1037	30,63	1070	31,60
972	28,71	1005	29,68	1038	30,66	1071	31,63
973	28,74	1006	29,71	1039	30,69	1072	31,66
974	28,77	1007	29,74	1040	30,72	1073	31,69
975	28,80	1008	29,77	1041	30,75	1074	31,72
976	28,83	1009	29,80	1042	30,78	1075	31,75
977	28,86	1010	29,83	1043	30,81	1076	31,78
978	28,89	1011	29,86	1044	30,84	1077	31,81
979	28,92	1012	29,89	1045	30,87	1078	31,84